



SAFETY ALERT

No: SA 2020.02

Date: 14.07.2020

Subject: Magni M16 Rotax 912/914 Oil tank mounting bracket

Background

While carrying out routine cleaning & inspection, the pilot and owner of a Magni M16 gyroplane noticed the Rotax 912 Oil tank top horizontal support/mounting bracket to be cracked along the weld join and observed to be fully separated from the vertical support. The gyroplane had flown 630 hours.



Operations and Training Manager

Jeff Blunt

E-mail: trainingmanager@asra.org.au

Mobile: 0421 784088

AUSTRALIAN .SPORT ROTORCRAFT.ASSOCIATION



Alert

It is recommended that Magni M16 pilots and owners complete an inspection of the Rotax 912 Oil tank top horizontal support/mounting bracket prior to the next flight and during pre-flight inspections

Jeff Blunt
ASRA Operations Manager.