



SAFETY ALERT

No: 2019.01

Date: 20.06.2019

Subject: Jack Allen Rotor Heads

A search of the ASRA data base has identified registered gyroplanes fitted with a Jack Allen Rotor head. Owners have been contacted directly.

During a recent overhaul of one of these rotor heads, it was observed that the teeter bolt in use was a commercial grade bolt and not an AN Aircraft grade bolt as required by the ASRA construction standard.

Please immediately check that your aircraft is fitted with AN grade bolts in critical flight areas from the control stick to rotors as required by the ASRA construction standard.

Jeff Blunt
ASRA Operations Manager