

AUSTRALIAN .SPORT ROTORCRAFT.ASSOCIATION



SAFETY DIRECTIVE

No. SD 2019.02

Date of issue: 12th December 2019.

SUBJECT: Gyroplanes fitted with aluminium main rotor blades made by Aviation Artur Trendak Company or Cellier Aviation Company.

Refer to the attached Safety Directive Nr SP -0004-2019-A, issued by the Republic of Poland Civil Aviation Authority. *With immediate effect, all Australian gyroplanes of this type are grounded*, pending the completion of the corrective actions described in the above referenced Polish Safety Directive. Please note the requirements include dye penetrant inspection of the root part of the blades prior to the next flight, on-going frequent inspections and limited service life.

Jeff Blunt
ASRA Operations Manager.

Operations and Training Manager
Jeff Blunt
E-mail: trainingmanager@asra.org.au
Mobile: 0421 784088